Replace the Rollers of the Xtran Pinch

https://vimeopro.com/oceitcdoctrans/oce-colorado-1650-maintenance/video/369523988

Revision #1
Created 13 June 2022 16:44:09 by Richard McCombe
Updated 13 June 2022 16:44:37 by Richard McCombe