Errors & Fixes

A list of errors and fixes

- SYSTEM HALT (2) 51f:CAP SENS

SYSTEM HALT (2) 51f:CAP SENS

SYSTEM HALT (2)

51f:CAP SENS

image-1698072700795.jpg

Image not found or type unknown

To solve this issue, you may need Bike Grease (as below)

image-1698072672776.png

Image not found or type unknown

Apply dots of bike grease along the carriage rails.

image-1698072853773.png

Image not found or type unknown

Slide the carriage out of the station back and forth to spread the grease along the rails.

image-1698072983455.png

Image not found or type unknown