

# SYSTEM HALT (2) 51f:CAP SENS

## SYSTEM HALT (2)

### 51f:CAP SENS

[image-1698072700795.jpg](#)  
Image not found or type unknown

To solve this issue, you may need Bike Grease (as below)

[image-1698072672776.png](#)  
Image not found or type unknown

Apply dots of bike grease along the carriage rails.

[image-1698072853773.png](#)  
Image not found or type unknown

Slide the carriage out of the station back and forth to spread the grease along the rails.

[image-1698072983455.png](#)  
Image not found or type unknown

---

Revision #1

Created 1 September 2022 14:34:26 by Matt Parris

Updated 23 October 2023 15:01:10 by Matt Parris